

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

House
On dirt road .1 mile south of U.S. Route 1
(Baltimore Pike), .1 mile west of intersection
with U.S. Route 322 (Conchester Road)
Concordville (Concord Township)
Delaware County
Pennsylvania

HABS No. PA-174

4486
PA,
23-CON,
2-

Documentation: 3 exterior photos (1968)
11 interior photos (1968)
(photos taken during dismantling of
house, show frame construction)

George Eisenman, Photographer 1968

PA-174-1 NORTH FRONT

PA-174-2 WEST SIDE

PA-174-3 EAST SIDE AND NORTH FRONT

PA-174-4 FIRST FLOOR, FIREPLACE IN NORTHEAST CORNER

PA-174-5 FIRST FLOOR, WEST WALL, SHOWING FIREPLACE, CLOSET AND STAIRWAY

PA-174-6 FIRST FLOOR, WEST WALL, FIREPLACE WITH BAKE OVEN AND WOODEN CRANE

PA-174-7 FIRST FLOOR, NORTH WALL, SHOWING FRAME CONSTRUCTION ABOVE FRONT DOOR

PA-174-8 SECOND FLOOR, NORTH WALL

PA-174-9 SECOND FLOOR, FIREPLACE IN NORTHEAST CORNER

PA-174-10 SECOND FLOOR, WEST WALL, SHOWING CHIMNEY AND STAIRWAY

PA-174-11 SECOND FLOOR, SOUTH WALL

PA-174-12 SECOND FLOOR, DETAIL OF NORTHWEST CORNER, SHOWING FRAME CONSTRUCTION

(continued)

PA-174-13 ATTIC, WEST WALL, SHOWING CHIMNEY AND ROOF STRUCTURE

PA-174-14 BASEMENT, WEST WALL, SHOWING STAIRWAY AND STONE ARCH SUPPORTING
FIRST-FLOOR FIREPLACE